

水準点現況調査写真

調査年月日 平成 21 年 11 月 日

標 識 番 号	1 8
所 在 地	横浜市鶴見区末広町一丁目 11
 A close-up photograph of a leveling point marker. The marker is a white cylindrical post with a red band at the top, mounted on a black tripod. The tripod is positioned on a concrete base. The ground is covered with dry leaves and some trash.	
 A photograph showing the leveling point marker in its location. The marker is on a concrete base next to a metal railing. In the background, there is a bridge with a road and some trees. A sign with Japanese text is visible on the railing.	
備 考	： 鶴見大橋際